Implementation Status and Proposed Amendments to the Indoor Air Cleaner Regulation

California Air Resources Board Public Workshop and Webcast

June 12, 2009 9:30 a.m.

Byron Sher Auditorium, 2nd floor Cal/EPA Building 1001 I Street, Sacramento, CA



- Introduction and workshop purpose
- Regulation requirements
- Implementation
- Possible amendments
- Timeline
- How to submit comments
- Further information
- Questions and answers

Introduction and workshop purpose

- Update on implementation status
- Obtain input on possible changes to the air cleaner regulation

- Introduction and workshop purpose
- Regulation requirements
- Implementation
- Possible amendments
- Timeline
- How to submit comments
- Further information
- Questions and answers

Regulation requirements

- Adopted Sept. 2007; effective Oct. 18, 2008
- Air cleaners sold in CA after Oct. 18, 2010 must be tested, certified and labeled
- Labeling and advertising
- Manufacturers must notify distributors, retailers and sellers by Oct. 18, 2009 and send contact information to ARB
- Recordkeeping

- Introduction and workshop purpose
- Regulation requirements
- Implementation
- Possible amendments
- Timeline
- How to submit comments
- Further information
- Questions and answers

Implementation

- Held workshop in December 2008 to discuss implementation steps
- Developed and posted certification application and procedures
- Translated regulation into Chinese and Korean (will be posted soon)
- Posted Q & As and we are responding to individual questions
- Audited two laboratories
- Posted list of certified air cleaners on web site

Implementation – ozone testing and certification

- Testing facilities approved for ANSI/UL 867 ozone test
 - UL/AQS approved; Intertek audited, completion pending
 - 14 models from 7 companies tested
- Air cleaners certified
 - 36 models certified (34 mechanical and 2 ionizers)
 - Slower rate than anticipated

Problems identified

- Only one testing facility approved; however, it's not being fully utilized
- Several steps in ozone test protocol have lengthened the test time beyond expectations; testing costs higher than expected
- Economic downturn and lower consumer demand have resulted in higher than expected inventories of air cleaners
- More in-duct ozone generators marketed than previously recognized

- Introduction and workshop purpose
- Regulation requirements
- Implementation
- Possible amendments
- Timeline
- How to submit comments
- Further information
- Questions and answers

Possible amendments

- Extend October 2010 compliance date
- Extend allowable date for use of adhesive sticker labels
- Increase allowable test facilities for mechanical air cleaner testing
- Clarify ANSI/UL 867 Section 37 ozone test protocol (with UL)
- Limit exemption for in-duct devices

Extend October 2010 compliance date

- Extend compliance date by six months
- Rationale: extension requested by manufacturers due to delay in readiness of second testing laboratory and excess inventories due to economic downturn

Increase allowable test facilities for mechanical air cleaner testing

- Allow NRTLs, recognized by OSHA to perform ANSI/UL Standard 507 testing, to accept testing under OSHA Programs 2, 3 and 4, subject to NRTL evaluation/approval
- Rationale: no ozone risk from mechanical devices; additional facilities can perform ANSI/UL Standard 507 electrical safety test

Clarify ozone test protocol - I

- UL to clarify criteria for stopping ozone tests at 8 hours vs. 24 hours
 - Concern: Too restrictive as implemented; penalizes low-emitting devices
 - Solution: Revise definition of steady state at hour 7-8
- Streamline chamber performance tests
 - Concern: Sec. 37.2.3 requirements take more than two days of testing
 - Solution: Verify ozone half-life once before each model group test; conduct other tests biannually



Clarify ozone test protocol - II

- Streamline filter tests
 - Concern: Multiple types of filters are sometimes shipped and all must be tested
 - Solution: Require testing of the least reactive (worst-case) alternate filter media, plus the standard filter
- Specify VOC and PM limits
 - Concern: Chamber filtration are required, but only ozone background limits are specified
 - Solution: Specify maximum chamber concentrations of VOCs and PM, too

Address in-duct devices

- Concern: more in-duct devices being marketed, and anecdotal reports of elevated ozone emissions
- Solution: Consider ban on in-duct technologies designed to intentionally produce ozone
- Looking for data on ozone emissions from in-duct air cleaners

- Introduction and workshop purpose
- Regulation requirements
- Implementation
- Possible amendments
- Timeline
- How to submit comments
- Further information
- Questions and answers

Timeline

- June 12, 2009 workshop
- July 3, 2009 deadline for comments (requested by June 26, 2009)
- September 4, 2009 staff report released
- October 22-23, 2009 Board update and public hearing on possible amendments
- Final steps: 15-day notice if needed; submittal to Office of Administrative Law

- Introduction and workshop purpose
- Regulation requirements
- Implementation
- Possible amendments
- Timeline
- How to submit comments
- Further information
- Questions and answers

How to submit comments

- Written comments requested by June 26, 2009
- Written comments required by July 3, 2009
- Send electronically to: aircleaners@listserv.arb.ca.gov
- Send hard copies to:

Peggy Jenkins
Research Division, 5th floor
California Air Resources Board
1001 I Street
P.O. Box 2815
Sacramento, CA 95812



Further information

Air cleaner regulation web page:

http://www.arb.ca.gov/research/indoor/aircleaners/aircleaners.htm

Certification application:

http://www.arb.ca.gov/research/indoor/aircleaners/certification.htm

Please sign up for email list serve updates:

http://www.arb.ca.gov/listserv/listserv.php

- Staff contacts:
 - Certification and testing:
 Ryan Johnson 916-323-2190 rjohnson@arb.ca.gov
 - General information:
 Jim Behrmann 916-322-8278 jbehrman@arb.ca.gov

Questions and answers

- Ways to submit questions email to: auditorium@calepa.ca.gov
- Phone in to: 1-877-784-3238, Passcode 29039, Leader's name: Peggy Jenkins
- Thank you for your participation!